



back of the door

door edge

door frame

door edge

front of the door





wooden door: ①②④⑥ are holes without piercing the door panel. ③⑤ are holes drilled the whole door panel through.

door edge

door frame

door edge

front of the door




wooden door: ①②④⑥ are holes without piercing the door panel. ③⑤ are holes drilled the whole door panel through.

door edge

door frame

door edge

front of the door



For metal door: ①④⑥ will be welding fixed and no need to drill holes. ② is a hole without piercing it while ③⑤ drill the whole door panel through.